


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-269	Smoke	9/2/2009	ADS/TM	S11MM1016MH	Dry	Yes	701.36



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-269	Smoke	9/2/2009	ADS/TM	S11MM1016MH	Dry	Yes	701.36

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11MM1016G1	S11MM1016MH	S11MM1013MH	159.08	8
S11MM1012G1	S11MM1012MH	S11MM1016MH	138.262	8
S11MM1009G1	S11MM1009MH	S11MM1016MH	165.65	8
S11MM1022G1	S11MM1022MH	S11MM1009MH	46.5243	8
S11MM1034G1	S11MM1034MH	S11MM1022MH	191.844	8

Observations & Photos

Obs_ID S1028-269-OB01

Address 3109 Virginia Ave


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1016MH

Comments Smoke from service lateral in back yard. 3109 Virginia Ave.



Picture \S1028-269-OB01-P01.jpg

Comments Back of house, 3109 Virginia Ave.

Obs_ID S1028-269-OB02

Address 3105 Virginia Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S11MM1012MH

Comments Smoke from cleanout in back yard. 3105 Virginia Ave.



Picture \S1028-269-OB02-P01.jpg

Comments Back of house, 3105 Virginia Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-269	Smoke	9/2/2009	ADS/TM	S11MM1016MH	Dry	Yes	701.36

Obs_ID S1028-269-OB03

Address 3103 Virginia Ave


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1012MH

Comments Smoke from service lateral in back yard. 3103 Virginia Ave.



Picture \S1028-269-OB03-P01.jpg

Comments Back yard, 3103 Virginia Ave.

Obs_ID S1028-269-OB05

Address 4669 Delaware Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S11MM1016MH

Comments Smoke from cleanout in back yard. 4669 Delaware Ave.



Picture \S1028-269-OB05-P01.jpg

Comments Back yard, 4669 Delaware Ave.

Obs_ID S1028-269-OB04

Address 3101 Virginia Ave


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1012MH

Comments Smoke from service lateral in back yard. 3101 Virginia Ave.



Picture \S1028-269-OB04-P01.jpg

Comments Back of house, 3101 Virginia Ave.

Obs_ID S1028-269-OB06

Address 3123 Virginia Ave


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1016MH

Comments Smoke from service lateral in back yard. 3123 Virginia Ave.



Picture \S1028-269-OB06-P01.jpg

Comments Back of house, 3123 Virginia Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-269	Smoke	9/2/2009	ADS/TM	S11MM1016MH	Dry	Yes	701.36

Obs_ID S1028-269-OB07

Address 3125 Virginia Ave

Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1016MH

Comments Smoke from service lateral in back yard. 3125 Virginia Ave.



Picture \S1028-269-OB07-P01.jpg

Comments Back yard, 3125 Virginia Ave.

Obs_ID S1028-269-OB09

Address 3131 Virginia Ave


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1013MH

Comments Smoke from service lateral in back yard. 3131 Virginia Ave.



Picture \S1028-269-OB09-P01.jpg

Comments Back of house, 3131 Virginia Ave.

Obs_ID S1028-269-OB08

Address 3127 Virginia Ave

Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1016MH

Comments Smoke from service lateral in back yard. 3127 Virginia Ave.



Picture \S1028-269-OB08-P01.jpg

Comments Back of house, 3127 Virginia Ave.

Obs_ID S1028-269-OB10

Address 3133 Virginia Ave


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1013MH

Comments Smoke from service lateral in back yard. 3133 Virginia Ave.



Picture \S1028-269-OB10-P01.jpg

Comments Back of house, 3133 Virginia Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-269	Smoke	9/2/2009	ADS/TM	S11MM1016MH	Dry	Yes	701.36

Obs_ID S1028-269-OB11

Address 4661 Delaware Ave

Status Private

Source Service Lateral

Location Field / woods

Nearest MH S11MM1016MH

Comments Smoke from service lateral in empty lot. 4661 Delaware Ave.



Picture \S1028-269-OB11-P01.jpg

Comments Back of lot, 4661 Delaware Ave.

Obs_ID S1028-269-OB13

Address 4656 Pimlico Rd


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1009MH

Comments Smoke from service lateral in back yard. 4656 Pimlico Rd.



Picture \S1028-269-OB13-P01.jpg

Comments Back of house, 4656 Pimlico Rd.

Obs_ID S1028-269-OB12

Address 4660 Pimlico Rd


Status Private

Source Service Lateral

Location Paved concrete

Nearest MH S11MM1016MH

Comments Smoke from service lateral in paved concrete behind house. 4660 Pimlico Rd.



Picture \S1028-269-OB12-P01.jpg

Comments Back of house, 4660 Pimlico Rd.

Obs_ID S1028-269-OB14

Address 4653 Delaware Ave

Status Private

Source Service Lateral

Location Field / woods

Nearest MH S11MM1009MH

Comments Smoke from service lateral in empty lot. 4653 Delaware Ave.



Picture \S1028-269-OB14-P01.jpg

Comments Back of lot, 4653 Delaware Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-269	Smoke	9/2/2009	ADS/TM	S11MM1016MH	Dry	Yes	701.36

Obs_ID S1028-269-OB15

Address 4652 Pimlico Rd


Status Private

Source Service Lateral

Location Paved concrete

Nearest MH S11MM1022MH

Comments Smoke from service lateral in paved concrete behind house. 4652 Pimlico Rd.



Picture \S1028-269-OB15-P01.jpg

Comments Back of house, 4652 Pimlico Rd.

Obs_ID S1028-269-OB17

Address 4648 Pimlico Rd

Status Private

Source Service Lateral

Location Paved concrete

Nearest MH S11MM1022MH

Comments Smoke from service lateral in paved concrete behind house. 4648 Pimlico Rd.



Picture \S1028-269-OB17-P01.jpg

Comments Back of house, 4648 Pimlico Rd.

Obs_ID S1028-269-OB16

Address 4650 Pimlico Rd


Status Private

Source Service Lateral

Location Paved concrete

Nearest MH S11MM1022MH

Comments Smoke from service lateral in paved concrete behind house. 4650 Pimlico Rd.



Picture \S1028-269-OB16-P01.jpg

Comments Back of house, 4650 Pimlico Rd.

Obs_ID S1028-269-OB18

Address 4644 Pimlico Rd

Status Private

Source Cleanout

Location Yard - back

Nearest MH S11MM1022MH

Comments Smoke from cleanout in back yard. 4644 Pimlico Rd.



Picture \S1028-269-OB18-P01.jpg

Comments Back of house, 4644 Pimlico Rd.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-269	Smoke	9/2/2009	ADS/TM	S11MM1016MH	Dry	Yes	701.36

Obs_ID S1028-269-OB19

Address 4630 Pimlico Rd


Status Private

Source Cleanout

Location Yard - back

Nearest MH S11MM1022MH

Comments Smoke from cleanout (missing cap) in back yard. 4630 Pimlico Rd.



Picture \S1028-269-OB19-P01.jpg

Comments Back of house, 4630 Pimlico Rd.

Obs_ID S1028-269-OB21

Address 4646 Pimlico Rd


Status Private

Source Service Lateral

Location Paved concrete

Nearest MH S11MM1022MH

Comments Smoke from service lateral in paved concrete behind house. 4646 Pimlico Rd.



Picture \S1028-269-OB21-P01.jpg

Comments Back of house, 4646 Pimlico Rd.

Obs_ID S1028-269-OB20

Address 4648 Pimlico Rd

Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1022MH

Comments Smoke from service lateral in back yard. 4648 Pimlico Rd.



Picture \S1028-269-OB20-P01.jpg

Comments Back of house, 4648 Pimlico Rd.

Obs_ID S1028-269-OB22

Address 4646 Pimlico Rd


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1022MH

Comments Smoke from service lateral in back yard. 4646 Pimlico Rd.



Picture \S1028-269-OB22-P01.jpg

Comments Back of house, 4646 Pimlico Rd.